


Combinations of Corrosion and Fatigue Failure of Wire Rope in High-Current Environments

Presented by Eric McCorquodale, BEng, EIT
Durability of Cables and Moorings in Tidal Flows
31 March 2016

www.jasco.com




JASCO Applied Sciences Ltd

- Specialist Acoustic and Bio-acoustic Consultancy
- Acoustic instrumentation R&D and manufacture – 25 years experience
- Global capability
 - Canada - Victoria BC, Halifax NS
 - USA - Washington DC, Anchorage AK, Ithaca
 - Southampton, UK
 - Brisbane, Australia
- Clients
 - Oil & Gas Multi-Nationals
 - Construction
 - Military
 - Government, Academia
- Staff
 - 76 staff, multiple PhDs - Acoustics, Engineering, Electronics, Software, Oceanography, Bioacoustics
- Example projects
 - Sakhalin (Vessel and oil activity noise measurement and monitoring), Chukchi Sea (49,000 km² recording programme), Falkland Islands (Cetacean and noise recording Programme), Alaska (Shell drilling programme vessel, sonar rig noise), Gulf of Mexico (Deep water vessel noise measurement), North Sea (Ambient, power generation, renewable energy noise + particle velocity), Great Barrier Reef (noise and marine life)



Tidal Environments


- Bay of Fundy
- Cook Inlet, Alaska
- Bristol Channel, UK
- Tappan Zee, New York
- Uldolmok Strait, South Korea



Bay of Fundy, 2012

Difficulties


- Knockdown



Memorial University, CSAR Flume Tank, 2009

Difficulties

- Strumming
- Vortex-Induced Vibrations



Gif Credit: Cesareo de La Rosa Siqueira, 2005


Difficulties

- High Forces
- Movement
- Waves



Acoustic Monitoring

- Flow noise
 - Mooring-created eddies
 - “Pseudo-noise”
- Hydrodynamic moorings
 - SUBS
 - High-Flow shields



High-Flow Mooring



The Problem

Corrosion of Wire Rope

- Accelerated corrosion
 - Current
 - Abrasion
- Constant movement
 - Strumming
 - Fatigue
 - Torsion
 - Flexing



Solutions

Material choices

- 316 SS
- Titanium
- Galvanized Steel



Isolation

- Prevent galvanic potential
- Sacrificial anodes



Coatings

- Remove electrolyte

Photo Credit: Mooring Systems Inc.

The Facebook Post





Photo Credit: Jason Wood, 2015

The Project

October 2015

- 5 recorders
- Range of currents
- Range of depths
- Tidal zone
- Fishing zone




The Rest of the Mooring

- Washed ashore



- Both ends severed

The Acoustic Data



The Investigation

- No isolation
- Partial coating
- No sacrificial anodes



The Bucket

- High temperature
- High Salinity
- High Oxygen Content



The Mechanism

Our Break

- 40 lb load



Tension break

- 18 000 lb breaking load




The Remaining Moorings

- 3 moorings successfully retrieved
- Floats retrieved from remaining mooring
- Recorder found on beach
- All had same problems
- Same characteristic failure mechanism



Current vs Corrosion



Increasing Current

Moving forward

- Anodes
- Isolation
- Thicker strand wire
- Complete coating or no coating
- 316 SS wire
- Inhibit movement

Questions?

